



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GTN 6XX/7XX Owner/Operators

DATE: December 20, 2012

SUBJECT: This communication is intended to inform Garmin aviation customers of forthcoming service document Software Service Bulletin 1236 GTN 6XX/7XX Software Upgrade Software Version 3.00, COM Software Version 2.10, NAV Software Version 6.02, NAV FPGA Version 1.1, WAAS Software Version 5.0, and GMA 35 Software Version 2.20.

COMPLIANCE

Recommended

PURPOSE

This Service Bulletin announces the availability of GTN 6XX/7XX Main Software Version 3.00, COM Software Version 2.10, NAV Software Version 6.02, NAV FPGA Version 1.1, WAAS Software Version 5.0, and GMA 35 Software Version 2.20.

PRODUCTS AFFECTED

Model	Garmin PN	Main SW PN/ Main SW Version	COM SW PN/ COM SW Version	NAV SW PN/ NAV SW Version	NAV FPGA PN/ NAV FPGA Version	WAAS SW PN/ WAAS SW Version
GTN 625	011-02254-00	006-B1026-10/ 3.00	N/A	N/A	N/A	006-B0339-20/ 5.0
GTN 635	011-02255-00	006-B1026-10/ 3.00	006-B1061-04/ 2.10	N/A	N/A	006-B0339-20/ 5.0
GTN 650	011-02256-()	006-B1026-10/ 3.00	006-B1061-04/ 2.10	006-B0082-12/ 6.02	006-C0124-01/ 1.1	006-B0339-20/ 5.0
GTN 725	011-02281-00	006-B1026-10/ 3.00	N/A	N/A	N/A	006-B0339-20/ 5.0
GTN 750	011-02282-()	006-B1026-10/ 3.00	006-B1061-04/ 2.10	006-B0082-12/ 6.02	006-C0124-01/ 1.1	006-B0339-20/ 5.0

The following software versions in the GMA 35 unit (Garmin PN 011-02299-00) are affected:

Software Description	SW PN	SW Version
Audio Software	006-B0773-03	2.20
ARC DB	006-D3035-24	2.20
Auxiliary Software	006-B0772-03	2.20
Audio Data	006-D3034-10	2.10
Grammar	006-D3034-14	2.20

DESCRIPTION

This software service bulletin describes the process for upgrading the GTN 6XX/7XX Series Unit's Main Software to version 3.00 and the other software versions listed above in the Purpose Section of this bulletin.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.