



## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered Garmin GTN Owner/Operators

**DATE:** April 30, 2013

**SUBJECT:** This communication is intended to inform Garmin aviation customers of forthcoming service document Service Bulletin 1315: STC SA01933LA-D approval for GNS 400W/500W Series Unit's Software Upgrade to Main Software Version 5.03 and GPS Software 5.0

**CERTIFICATION**

**APPROVAL:** STC SA01933LA-D MDL Revision G Update

**COMPLIANCE**

Optional

**PURPOSE**

This Service Bulletin provides notification of STC SA01933LA-D Master Drawing List revision G and the following software update:

- GNS 400W/500W Series Main Software version 5.03 and GPS/WAAS Software version 5.0.

Approves the following additional interfaces:

- GTN crossfill (i.e. the sharing of user waypoints and transferring the active flight plan from a GTN to a GNS)
- Garmin's GDL 88 ADS-B transceiver
- Collins HSI 84 Nav Indicator
- Collins FD-112V Nav Indicator
- SPZ 200A/500 autopilot

For additional changes to the GNS 400W/500W software, refer to Service Bulletin No. 1317.

**PRODUCTS AFFECTED**

Aircraft modified by STC SA01933LA-D for installation of GNS 400W series and GNS 500W series equipment.

**DESCRIPTION**

This Service Bulletin provides instructions for incorporating the GNS 400W/500W Series Main Software version 5.03 and GPS/WAAS Software version 5.0 approved by MDL Rev G.

Refer to Service Bulletin No. 1317 for instructions for loading the software in the GNS 400W/500W units.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.