

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GTN 6XX/7XX Owner/Operators

DATE: October 1, 2013

SUBJECT: GTN 6XX/7XX Software Upgrade to COM Software Version 2.12 and GMA 35 ARC Database

Version 3.08

CERTIFICATION

APPROVAL: TSO Authorization (see Approval section of SSB 1356 for details)

COMPLIANCE

Optional

PURPOSE

This Service Bulletin announces the availability of GTN 6XX/7XX COM Software Version 2.12 and GMA 35 ARC DB Version 3.08.

GTN 6XX/7XX COM Software Version 2.12 contains the following changes from Version 2.11:

 COM Software Version 2.12 provides improved squelch control over Version 2.11. It is helpful only in those installations that experience open squelch (receiver too sensitive) after utilizing the COM Monitor Mode.

GMA 35 ARC Software Version 3.08 contains the following changes from Version 3.05:

• Mutes telephone audio during an aural alert.

PRODUCTS AFFECTED

The following GTN units are affected:

	GTN 625	GTN 635	GTN 650	GTN 725	GTN 750
Garmin PN	011-02254-00	011-02255-00	011-02256-()	011-02281-00	011-02282-()
COM SW PN/	N/A	006-B1061-06/	006-B1061-06/	IN/A	006-B1061-06/
COM SW Version		2.12	2.12		2.12

The following software versions in the GMA 35 unit (Garmin PN 011-02299-00) are affected:

Software Description	SW PN	SW Version
ARC DB	006-D3035-56	3.08

DESCRIPTION

This software service bulletin describes the process for upgrading the GTN 6XX/7XX Series Unit's COM Software to Version 2.12 and other software versions listed above in the Purpose Section of this bulletin.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.