

## **SERVICE ADVISORY**

**NO.: 1358 Rev A**

**TO:** Garmin Aviation Service Centers and Owners/operators of all Cirrus Perspective®, Embraer Prodigy™, G900X, G950, G1000, G2000, G3000, and G5000 Integrated Flight Deck Systems

**DATE:** October 17, 2013

**SUBJECT:** Synthetic Vision Technology (SVT) Pathways Boxes May Be Depicted Incorrectly

---

### **AFFECTED PRODUCTS**

All Cirrus Perspective®, Embraer Prodigy™, G900X, G950, and G1000 Integrated Flight Deck systems using GDU software v13.00 through 13.04, and G2/3/5XXX Integrated Flight Deck systems using GDU software v2.10 through 3.17.

### **ISSUE**

SVT Pathways boxes may be depicted at an altitude other than the selected altitude.

### **PILOT ACTION**

Garmin recommends the pilot disable the display of SVT Pathways if pathways boxes are depicted at an altitude other than the selected altitude when there is no vertical deviation indication (VDI) guidance.

---

### **RESOLUTION**

This issue will be resolved in a future software release.