

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered G1000-equipped Hawker Beechcraft King Air 200/300 Owners and Operators

**DATE:** February 26, 2014

**SUBJECT:** Nose bay cooling fan duct installation for G1000-equipped Hawker Beechcraft King Air

200/300 series aircraft

**CERTIFICATION** 

**APPROVAL:** STC SA01535WI-D (see Approval section of STC SB1375 for details)

**COMPLIANCE** 

Optional: May be incorporated at the owner's discretion and is not warranty reimbursable.

## **PURPOSE**

This STC Service Bulletin provides notification of the STC SA01535WI-D, MDL Revision 16 (200 series aircraft) and Revision 7 (300 series aircraft), for installation of the nose avionics bay cooling fan ducts that will improve cooling performance and eliminate the G1000 airworthiness limitation for fan operational and annunciator checks every 220 hours. Maintenance interval checks are still applicable for the nose avionics bay fans.

## **PRODUCTS AFFECTED**

G1000-equipped Hawker Beechcraft King Air 200/300 series aircraft.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.