

SERVICE ADVISORY

NO.: 1416 Rev A

TO: Owners and Operators of Garmin G1000-equipped Socata TBM 850/900 models

DATE: March 28, 2014

SUBJECT: Connex Data Not Being Displayed

AFFECTED PRODUCTS

Connex flight data service enabled G1000-equipped Socata TBM 850/900 installations with GDU software version 14.01 installed with a GDL 69(A) are affected by this bulletin.

ISSUE

Connex data will not be displayed unless **all** of the following conditions are true:

- The GDL 69(A) has an active XM weather subscription
- The aircraft is within XM coverage and the GDL 69(A) has XM reception

RESOLUTION

Garmin plans to correct this issue in a future software release.