



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record for the GTN 635/650/750
DATE: April 1, 2015
SUBJECT: GTN 635/650/750 Software Upgrade to COM Software Version 2.20

CERTIFICATION APPROVAL: TSO Authorization (see Approval section of SB1526 for details)

COMPLIANCE

Optional

PURPOSE

This Service Bulletin announces the availability of GTN 635/650/750 COM Software Version 2.20 and COM FPGA Version 2.4.

GTN 6XX/7XX COM Software Version 2.20/FPGA Version 2.4 contain the following changes from COM Software Version 2.13/FPGA Version 2.2:

- Reduced noise burst (“Squelch Tail”) that occurs at the end of a reception
- Reduced random squelch breaks (popping)

PRODUCTS AFFECTED

The following units are affected:

Model	Appliance P/N
GTN 635	011-02255-00
GTN 650	011-02256-()
GTN 750	011-02282-()

DESCRIPTION

This Service Bulletin describes the process for upgrading the GTN 635/650/750 Series Unit’s COM Software to Version 2.20 and other software versions listed above in the Purpose Section of this bulletin.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin’s authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.