



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GPSMAP 495 and GPSMAP 496 Owners of Record
DATE: July 29, 2015
SUBJECT: Discontinued Repair Service for GPSMAP 495 and GPSMAP 496 units

PRODUCTS AFFECTED

The GPSMAP 495 and GPSMAP 496 products are affected.

DISCUSSION

Effective immediately, repair services are discontinued for the products listed above.

Applicable databases will still be available for download from www.FlyGarmin.com.

We sincerely regret discontinuing service or support on any Garmin product. However, a number of components required for the manufacture and/or repair of essential subassemblies within the affected products are no longer available.

Please visit www.Garmin.com/aviation for your product replacement needs.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.