

## **SERVICE ADVISORY**

**NO.: 1574 Rev A**

**TO:** Garmin Aviation Service Centers, Distributors, and Owners of Record

**DATE:** November 16, 2015

**SUBJECT:** GTN 6XX/7XX User-Defined Waypoints

---

### **PRODUCTS AFFECTED**

Garmin GTN 6XX/7XX series units with main software version 6.01 and earlier are affected.

### **ISSUE**

Modifying the location of a user-defined waypoint that is part of an active flight plan may result in erroneous navigation.

### **PILOT ACTION**

Do not modify the location of a user-defined waypoint that is part of an active flight plan.

### **RESOLUTION**

A future GTN 6XX/7XX software release will correct this issue.