

## **SERVICE ADVISORY**

**NO.: 1648 Rev A**

**TO:** Owners and Operators of Garmin G3000 and G5000 systems installed in Cessna Sovereign+, Citation X+, Citation CJ3+, and M2 aircraft

**DATE:** August 3, 2016

**SUBJECT:** SurfaceWatch™

---

### **AFFECTED PRODUCTS**

- G3000 Pilot's Guide for the Cessna Citation CJ3+ (190-01742-01) Rev A
- G3000 Pilot's Guide for the Cessna Citation M2 (190-01578-01) Rev B
- G5000 Pilot's Guide for the Cessna Citation Sovereign+ (190-01581-01) Rev A
- G5000 Pilot's Guide for the Cessna Citation X+ (190-01664-01) Rev B

### **ISSUE**

SurfaceWatch 'rejected takeoff' and 'landing rollout' voice callouts documented in the above Pilot's Guides are incorrect.

### **Pilot Action**

Make a conspicuous note in the relevant section of the affected Pilot's Guides to reflect the following:

During a rejected takeoff, distance remaining voice callouts are issued for the remaining runway distances of:

- 5000'
- 4000'
- 3000'
- 2000'
- 1000'
- 500'
- 100'

During a landing rollout, distance remaining voice callouts are issued for the remaining runway distances of:

- 3000'
- 2000'
- 1000'
- 500'
- 100'