



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record of G1000-equipped King Air 200/300 Series Aircraft with Garmin GTS 8000 (TCAS II)

DATE: January 12, 2017

SUBJECT: G1000 System Software Version 0985.09 for G1000-equipped King Air 200/300 Series Aircraft with Garmin GTS 8000 (TCAS II)

CERTIFICATION APPROVAL: STC SA01535WI-D

COMPLIANCE

Optional

PURPOSE

G1000 System Software Version 0985.09 contains GTS 8000 Software Version 2.22. GTS 8000 Software Version 2.22 improves TCAS II resolution advisory audio message playback. Incorporating this service bulletin resolves the issue identified in Garmin Service Advisory 1685.

PRODUCTS AFFECTED

All G1000-equipped Beechcraft King Air 200 and 300 series aircraft with G1000 System Software Versions 0985.07 or 0985.08 and a Garmin GTS 8000 (TCAS II) are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.