



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Owners of Record of G1000 NXi equipped King Air 200/300 Series Aircraft

DATE: October 6, 2017

SUBJECT: G1000 NXi System Software Version 2286.05 for G1000 NXi equipped King Air 200/300 Series Aircraft

CERTIFICATION APPROVAL: STC SA01535WI-D

COMPLIANCE

Optional

PURPOSE

G1000 NXi System Software version 2286.05 corrects an issue that may cause a "Traffic Fail" system alert message to appear in installations where TIS-A data from the #2 transponder (GTX 335R or GTX 33) is not desired.

PRODUCTS AFFECTED

All G1000 NXi equipped King Air 200 and 300 series aircraft equipped with G1000 NXi System Software versions 2286.01, 2286.02, 2286.03, and 2286.04 that include a GTX 345R transponder not interfaced to a traffic system are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.