



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GTX 3X5(R) Owner and Operators
DATE: November 11, 2019
SUBJECT: Approval of GTX 345(R) ADSB software version 3.13
CERTIFICATION AUTHORIZATION: STC SA01714WI and EASA STC 10060873

COMPLIANCE

Recommended: Garmin recommends the incorporation of this service bulletin at the next scheduled service interval.

PURPOSE

This STC Service Bulletin provides notification of an update to STC SA01714WI and EASA STC 10060873, GTX 33X and GTX 3X5(R) with ADS-B AML STC, MDL Revision 15.

GTX 345(R) ADSB software version 3.13 fixes an issue where some traffic targets may be missed when over 200 targets are in range.

PRODUCTS AFFECTED

GTX 345/345R (GTX 3X5(R)) units installed using Part 23 ADS-B AML STC SA01714WI and EASA STC 10060873 are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.