



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GFC 500/Textron Aviation (Beechcraft) F33A Owners and Operators
DATE: January 30, 2020
SUBJECT: GFC 500 installed in F33A Gain Settings Update
CERTIFICATION AUTHORIZATION: STC SA01866WI

COMPLIANCE

Recommended. This service bulletin is recommended for Textron Aviation (Beechcraft) F33A aircraft (S/N CE-316 thru CE-1791) with GFC 500 systems installed per Part 23 AML STC SA01866WI. No other aircraft are affected by this update.

PURPOSE

This STC Service Bulletin provides notification of STC approval for installation of new GFC 500 gain settings for the Textron Aviation (Beechcraft) F33A (S/N CE-316 thru CE-1791) in accordance with STC SA01866W.

The new gain settings will provide improved performance in pitch modes of the GFC 500.

PRODUCTS AFFECTED

GFC 500 systems installed in Textron Aviation (Beechcraft) F33A, (S/N CE-316 thru CE-1791) by Part 23 AML STC SA01866WI are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.