

1200 E. 151st Street Olathe, KS 66062 913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GTS 825 and 855 Owner and Operators

DATE: March 23, 2020

SUBJECT: GTS Processor Main Software 3.14.1, added GI 275 and GTN Xi interfaces

CERTIFICATION

AUTHORIZATION: AML STC SA02121SE

COMPLIANCE

Recommended: Garmin recommends the incorporation of this STC Service Bulletin at the next scheduled service interval.

PURPOSE

This STC Service Bulletin provides notification of an update to the AML STC SA02121SE Master Drawing List revision 3.

MDL revision 3 includes the following changes:

- Updated GTS 825 and GTS 855 to main software version 3.14.1
 - Fixes an issue where some ADS-B traffic intruders may not be displayed when over 200 ADS-B intruders are within range



NOTE

Active TCAS surveillance is not affected by this issue.

· Added GI 275 and GTN Xi interfaces

PRODUCTS AFFECTED

GTS 825 and GTS 855 units installed under the GTS 8XX Part 23 AML STC SA02121SE are affected.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.