

SERVICE ADVISORY

NO.: 2073 Rev A

TO: GPSMAP 695/696 Owners and Operators
DATE: May 21, 2020
SUBJECT: GPSMAP 695/696 End of Service Life

PRODUCTS AFFECTED

Garmin GPSMAP 695/696 units are affected.

ISSUE

Repair services and service parts are discontinued for the GPSMAP 695/696 effective immediately.

We sincerely regret discontinuing service or support on any Garmin product. However, a number of components required for the manufacture and/or repair of essential subassemblies within the affected products are no longer available.

Please visit www.Garmin.com/aviation for your product replacement needs.