

1200 E. 151<sup>st</sup> Street Olathe, KS 66062 913-397-8200

#### **AVIATION SERVICE DOCUMENT NOTIFICATION**

**TO:** Garmin G1000<sup>®</sup> NXi King Air 200/300 Series Owner and Operators

**DATE:** March 31, 2022

SUBJECT: G1000 NXi STC Software Update for 200/300 Series Aircraft

**CERTIFICATION** 

**AUTHORIZATION:** STC SA01535WI-D

### **COMPLIANCE**

Optional: This STC Service Bulletin may be incorporated at the owner's discretion.

# **PURPOSE**

This service bulletin provides notification of an available update to System Software Version 2286.14 and includes the following changes:



# **NOTE**

With this update, the 'FDR with GIA64 Option' configuration – intended to support a 3<sup>rd</sup> party FDR STC - was removed from the software image. In the future, a separate supplemental loader image will be created that contains the updated GIA 64 FDR configuration.

- Support for -05 GEA<sup>™</sup> 71B LRU (allows removal of existing Meggitt Signal Conditioners)
- Support for -01 GTX<sup>™</sup> 345R LRU (end-of-life planning only, no functional change)
- Improvements to EIS transient indications for Prop RPM, Torque, and ITT
- · Addition of new features:
  - Standby Flight Plans
  - (Advisory) VNAV Guidance for Non-Precision Approaches
  - Fast Find
- Support for direct (analog) interface to Collins ALT-50A or ALT-55B Radio Altimeter
- GSU 75 software update to address susceptibility to reset in certain ground circumstances when operating without GPS aiding
- GSA 9XXX software and Rudder Boost performance updates (300/B300 only)
- Gain file updates for VNAV acknowledgment timeout and transition to approach force capture threshold improvements

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



1200 E. 151<sup>st</sup> Street Olathe, KS 66062 913-397-8200

# **PRODUCTS AFFECTED**

All Textron Aviation Inc. (Beechcraft) King Air 200 and 300 series aircraft equipped with G1000 Integrated Flight Deck per STC SA01535WI-D with system software versions 2286.06 through 2286.13 and equipped with all of the following LRUs:

- GIA 64E
- GMA 1360D
- GEA 71B
- GRS 7800/GDC 7400 or GSU 75B

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.