



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin GIA 64 Owner and Operators  
**DATE:** December 6, 2021  
**SUBJECT:** GIA 64 COM

---

### **COMPLIANCE**

Mandatory

### **PURPOSE**

One or both GIA 64 units may experience a total loss of COM when aircraft power input voltage is in the range of 5-7 VDC. This condition may be encountered temporarily during engine start and/or aircraft power bus switching.



### **NOTE**

Total loss of COM will persist until the affected GIA 64 units are power cycled.

This service bulletin contains instructions to return the affected product to Garmin.

### **PRODUCTS AFFECTED**

Garmin GIA 64 units purchased or installed since October 2021 listed in the link below are affected.

<https://support.garmin.com/en-US/?faq=arlmObxADx6EyleQMQ2pK7>

### **WARRANTY INFORMATION**

This Service Bulletin is warranty reimbursable with a deadline of May 31, 2022 after which this upgrade will no longer be reimbursable for labor.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.