

## **SERVICE ADVISORY**

**NO.: 2114 Rev A**

**TO:** GTX 345(D)R Owners and Operators  
**DATE:** February 19, 2021  
**SUBJECT:** Bluetooth Capability

---

### **PRODUCTS AFFECTED**

GTX 345(D)R units installed in G1000 NXi, G2000, G3000, and G5000 GIFD systems with the following software versions are affected:

- GDU/GTC software versions 20.50 through 20.93 AND GTX 345(D)R ADS-B software version 3.11 or later
- GDU/GTC software versions 21.00 through 21.55 AND GTX 345(D)R ADS-B software version 3.11 or later
- GDU/GTC software version 20.94 AND all GTX 345(D)R software versions

### **ISSUE**

The G1000 NXi, G2000, G3000, and G5000 will not list the GTX 345(D)R as an installed Bluetooth device.

#### **NOTE**

All other transponder functions work as intended, including ADS-B out and the ability to display traffic and FIS-B data on the GIFD display.

### **ACTION**

Be aware that Connex Setup is not available for pairing mobile devices to the GTX 345(D)R.

### **RESOLUTION**

This will be fixed in a future software release.

Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Garmin is under license. Other trademarks and trade names are those of their respective owners.