

1200 E. 151st Street Olathe, KS 66062 913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GTR 225 and GNC 255 Owners and Operators

DATE: May 2, 2024

SUBJECT: GTR 225/GNC 255 Display Software Version 3.02

CERTIFICATION

AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

Display Software Version 3.02 contains the following changes:

- Fixes the System ID to allow the frequency database to be updated
- Corrects the Glideslope flag on NMEA serial interface
- Prevents loading of software versions prior to 3.xx

© 2024 Garmin Ltd. or its subsidiaries.
This work is licensed under a

 $\underline{\text{Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License}}.$

PRODUCTS AFFECTED

GTR 225 and GNC 255 products listed below with Display Software 3.01 are affected.



NOTE

GTR 225 and GNC 255 products with part numbers ending in -00 or -20 should not install Display Software Version 3.02.

Table 1. Product Affected

Model	Appliance P/N	Serial Numbers
GTR 225	011-02718-40	6MJ0xxxxx
GTR 225A	011-02807-40	6MK0xxxxx
GTR 225B	011-02808-40	6ML0xxxxx
	011-02808-60	6ML2xxxxx
GNC 255A	011-02806-40	6MM0xxxxx
GNC 255B	011-02719-40	6MN0xxxxx
	011-02719-60	6MN2xxxxx

DOCUMENTATION CONSIDERATIONS

No changes were made to the Pilot's Guide for GTR 225/GNC 255 Display Software Version 3.02.



NOTE

The Pilot's Guides for Display Software Version 3.01 are applicable to Display Software Version 3.02.

- GTR 225/225A/225B Pilot's Guide (Garmin P/N 190-01182-00) Rev D or later
- GNC 255A/255B Pilot's Guide (Garmin P/N 190-01182-01) Rev E or later

WARRANTY INFORMATION

This modification is not warranty reimbursable.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.