



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GPS 175/GNX 375/GNC 355 Owner and Operators
DATE: August 23, 2021
SUBJECT: GPS 175/GNX 375/GNC 355 main software version 3.11
**CERTIFICATION
AUTHORIZATION:** AML STC SA02636SE

COMPLIANCE

Recommended: Compliance with this STC Service Bulletin is recommended at the next scheduled maintenance interval.

PURPOSE

This STC Service Bulletin provides notification of an update to STC SA02636SE GPS 175/GNX 375/GNC 355 Part 23 AML STC MDL Revision 10.

Major details of the update are:

- Updated GPS 175/GNX 375/GNC 355 main software to v3.11. This software corrects the inaccuracies of traffic targets position and fixes software issues in the GNX 375 identified in Service Advisory 2157. The software update also fixes software issues in GPS 175 and GNC 355 units.

PRODUCTS AFFECTED

GPS 175, GNX 375, GNC 355, or GNC 355A installed under GPS 175/GNX 375/GNC 355 Part 23 AML STC SA02636SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.