



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GFC 600H Bell 505 Owner and Operators
DATE: January 7, 2022
SUBJECT: DME Softkey

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion.

PURPOSE

The GFC 600H Bell 505 STC Equipment List Rev. 2, specifies the GIFD GFC 600H Option Loader Cards for original G1000H[®] and G1000H NXi systems. The option loader cards incorrectly configures the KN63 DME as enabled on the GIA RS-485 interface, causing the DME Softkey to show on the PFD.

Service Bulletin 22006 provides instructions on how to disable the DME Softkey on the PFD.

	CAS	SENSOR	PFD	OBS	CDI	DME	XPDR	IDENT	TMR/REF	NRST
--	-----	--------	-----	-----	-----	-----	------	-------	---------	------

Figure 1 DME Softkey

PRODUCTS AFFECTED

GFC 600H systems installed under the GFC 600H Bell 505 STC SR01961WI, Master Drawing List Revisions 1 through 5 in Bell Helicopters Model 505 (trade name *Jet Ranger X*) are affected.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.