



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GTS™ 8X0 Owners and Operators
DATE: January 7, 2022
SUBJECT: GTS 8X0 2020 IGRF Database for Non-GX000 Integrated Flight Deck Installations Only
CERTIFICATION AUTHORIZATION: TSO Authorization

COMPLIANCE

Recommended: Compliance with this service bulletin is recommended at the next regularly scheduled aircraft maintenance event.

PURPOSE

The 2020 IGRF Magnetic Field Model is now available.



NOTE

Installations with an expired IGRF database may have degraded ADS-B In performance when the aircraft is on the ground.

PRODUCTS AFFECTED

All GTS 8X0 (GTS 800/820/850) units interfaced to a GTN™ 6XX/7XX (Xi), GNS™ 4XX(W)/5XX(W), G500 (TXi), G500H, G600 (TXi), G700 TXi, G3X Touch™, GI 275, GMX 200, MX20, or other 3rd party flight display systems are affected.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.