



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Garmin G600 Owners and Operators  
**DATE:** July 12, 2022  
**SUBJECT:** TBM 700/850 with G600 approval to interface GFC 600 autopilot for RVSM operations

---

### **COMPLIANCE**

Optional. This STC Service Bulletin 22014 is optional and may be incorporated at the owner's discretion.

### **PURPOSE**

STC SA02153LA-D Master Drawing List Rev AB includes approval of G600/GFC 600 interfaces while maintaining RVSM capabilities.

### **PRODUCTS AFFECTED**

G600 installations in TBM 700/850 series aircraft modified under Supplemental Type Certificate (STC) SA02153LA-D are affected.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.