



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 22018 Rev B

**TO:** GTN™ Xi Owners and Operators  
**DATE:** January 27, 2023  
**SUBJECT:** Smart Glide™ Airport  
**REVISION B:** Added Resolution

---

### **PRODUCTS AFFECTED**

Garmin GTN Xi units with software version 20.20 and later with Smart Glide enabled are affected.

### **ISSUE**

An airport that is within glide range as depicted on the map may not be a selectable destination if it is less than 2NM away while flying at low altitude (less than 2500 feet AGL).

### **ACTION**

Maneuver and land without the use of Smart Glide.

### **RESOLUTION**

This has been fixed in GTN Xi Software Version 20.30. Refer to Garmin TSO Service Bulletin 22108.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a  
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).