



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GDC 7400 Owner and Operators
DATE: April 5, 2022
SUBJECT: GDC 7400 Pitot-Static Fittings

COMPLIANCE

Mandatory

PURPOSE

Due to a supplier machining defect, the pitot and/or static fittings may loosen within the connector plate. This creates a small path for debris and/or moisture incursion, as well as possible electromagnetic interference.

Garmin Service Bulletin 22029 contains instructions to return the affected product to Garmin.

PRODUCTS AFFECTED

Garmin GDC 7400 (011-02337-01) units listed in the link below are affected:

<https://support.garmin.com/en-US/aviation/faq/y3xGso4puD2oOqmO2GU3TA/>

WARRANTY INFORMATION

This Service Bulletin is warranty reimbursable with a deadline of October 31, 2022 after which this upgrade will no longer be reimbursable for labor.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.