



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GDU™ 620 Owner and Operators
DATE: May 5, 2022
SUBJECT: GDU 620 Software Version 7.41

CERTIFICATION

AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Optional: TSO Service Bulletin 22048 may be incorporated at the owner's discretion.

PURPOSE

GDU 620 software version 7.41 contains the following changes:

- Added Smart Glide™ capability when interfaced to a GTN™ Xi with Software Version 20.20 or later
- The display is now capable of annunciating situations where 3 vertical modes are armed with GFC 500

PRODUCTS AFFECTED

The following units are affected:

Table 1. Products Affected

Model	Appliance P/N
GDU 620 Display	011-01264-0()
GDU 620 Display	011-01264-1()
GDU 620 Display	011-01264-2()
GDU 620 Display	011-01264-3()
GDU 620 Display, Black Bezel	011-01264-5()
GDU 620 Display, Black Bezel, Right Hand	011-01264-6()

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.