



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 22060 Rev A

TO: G1000® NXi Owners and Operators
DATE: June 8, 2022
SUBJECT: Loading Databases

PRODUCTS AFFECTED

Garmin G1000 NXi with Software Versions GDU™ 20.59 and earlier are affected.

ISSUE

The G1000 NXi will not see databases (or will encounter syncing issues) when loading databases directly to the Flight Stream 510 using a computer.

ACTION

Do not load databases directly to the Flight Stream 510 using a computer. Use the Database Concierge WIFI to wirelessly transfer databases to the Flight Stream 510 or load the databases to a separate SD card.

RESOLUTION

This is fixed in G1000 NXi with Software Versions GDU 20.60 and later.

© 2022 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).