



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GTX™ 3X5(R) Owner and Operators
DATE: October 27, 2022
SUBJECT: Approval of GTX™ 3X5(R) Main Software Version 2.80, GPS Software Version 8.2, ADS-B Software Version 3.40, and new GTX 3X5 part numbers
CERTIFICATION AUTHORIZATION: SR02124SE MDL Revision 4

COMPLIANCE

Optional: STC Service Bulletin 22100 may be incorporated at the owner's discretion.

PURPOSE

This STC Service Bulletin provides notification of an update to STC SR02124SE, GTX 3X5(R) with ADS-B AML STC, MDL Revision 4.

Major details of the update are:

- Updated GTX 3X5 software to Main Software Version 2.80, GPS Software Version 8.2, and ADS-B Software Version 3.40. These updates improved AHRS algorithm for improved operation and robustness in GTX 345 models, and added Flight ID list to allow previously used Flight IDs to be rapidly selected.
- Added new GTX 335 and GTX 345 hardware part numbers, which have no functional improvements or changes to previous hardware.

There are no new rotorcraft models or functionality being added to the STC SR02124SE.

PRODUCTS AFFECTED

GTX 3X5(R) units installed using GTX 3XX Part 27 ADS-B AML STC SR02124SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.