



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Flight Stream 510 Owner and Operators
DATE: May 16, 2023
SUBJECT: Flight Stream 510 Software Version 2.72
**CERTIFICATION
AUTHORIZATION:** TSO Authorization

COMPLIANCE

Optional: Service Bulletin 23048 may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

Flight Stream 510 Software Version 2.72 is functionally equivalent to Flight Stream 510 Software Version 2.71. Flight Stream 510 Software Version 2.72 is required before downgrading software from Software Version 2.80 to any older software version.

PRODUCTS AFFECTED

Garmin Flight Stream 510 (011-03595-()) units with software version 2.71 or earlier are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.