



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** GPS 175/GNX 375/GNC 355, G500/G600 TXi, G500H TXi and GTN 6XX/7XX  
Owner and Operators

**DATE:** May 16, 2023

**SUBJECT:** Approval of Flight Stream Software Version 2.80 and 011-03595-10 Part Number

**CERTIFICATION  
AUTHORIZATION:** STC SA02636SE, SA02571SE, SR02622SE, SA02019SE-D, SR02120SE

---

### COMPLIANCE

Optional: Service Bulletin 23050 may be incorporated at the owner's discretion and is not warranty reimbursable.

### PURPOSE

This STC Service Bulletin provides notification of an update to the following MDLs:

- GPS 175/GNX 375/GNC 355 Part 23 AML STC Master Drawing List, 005-01206-A1, Rev. 16
- G500/G600 TXi Part 23 AML STC Master Drawing List, 005-00795-C2, Rev. 28
- G500H TXi Part 27 AML STC Master Drawing List, 005-01297-00, Rev. 10
- GTN 6XX/7XX Part 23 AML STC Master Drawing List, 005-00533-C0, Rev. 40
- GTN 6XX/7XX Part 27 AML STC Master Drawing List, 005-00533-H0, Rev. 12

Major details of the update are:

- Addition of new Flight Stream 510 part number 011-03595-10



### **NOTE**

011-03595-10 not approved for GTN 6XX/7XX units installed under STC SA02019SE-D or STC SR02120SE.

- Updated Flight Stream 510 software to Software Version 2.80:
  - Support for new Flight Stream 510 hardware
  - Improvements to Wi-Fi and Bluetooth robustness
- Requirement added for GWX™ 70/75 Software Version 2.30 or earlier when interfaced to a GTN 6XX/7XX or GTN Xi under STC SA02019SE-D

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

### **PRODUCTS AFFECTED**

The following products are affected:

- GPS 175/GNX™ 375/GNC® 355 Part 23 STC SA02636SE
- G500/G600 TXi Part 23 STC SA02571SE
- G500H TXi Part 27 AML STC SR02622SE
- GTN™ 6XX/7XX Part 23 AML STC SA02019SE-D
- GTN 6XX/7XX Part 27 AML STC SR02120SE

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.