

SERVICE ADVISORY

NO.: 23079 Rev A

TO: Aera Owners and Operators

DATE: August 7, 2023

SUBJECT: Aera End of Repair Service Life

PRODUCTS AFFECTED

The following products are affected:

- Aera 795
- Aera 796
- Aera 500
- Aera 510
- Aera 550
- Aera 560

ISSUE

Effective immediately, repair services are discontinued for the products listed above.

We sincerely regret discontinuing service or support for any Garmin product. However, a number of components required for the manufacture and/or repair of essential subassemblies within the affected products are no longer available.

Please visit www.Garmin.com/aviation for your product replacement needs.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a

Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License.