



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 23085 Rev A

TO: GTN™ Xi Owners and Operators
DATE: August 16, 2023
SUBJECT: TAWS-A Glideslope Deviation Alerts

PRODUCTS AFFECTED

TAWS-A enabled GTN Xi system with Main Software Versions 20.10 through 20.31 are affected.

ISSUE

Affected units will not generate TAWS-A glideslope deviation aural or visual alerts (Mode 5).

ACTION

Do not rely on TAWS-A glideslope deviation aural or visual alerting.

RESOLUTION

This has been fixed in GTN Xi Main Software Version 20.32. Refer to Garmin TSO Service Bulletin 23084.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/)..