



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G500H TXi Owner and Operators
DATE: August 23, 2023
SUBJECT: Approval of G500H TXi Main Software Version 3.51
CERTIFICATION AUTHORIZATION: STC SR02622SE MDL Rev 11

COMPLIANCE

Recommended: Compliance with this service bulletin is recommended at the next maintenance interval.

PURPOSE

Major details of the update are:

- G500H TXi Part 27 AML STC Equipment List (005-01297-01) updated to include references to new GSU 75H Mod Status
- G500H TXi main software version 3.51:
 - Fixed an issue where SVT™ could show erroneous terrain in the vicinity of airports.
 - Fixed an issue where a full SD card could result in loss of primary navigation instruments

PRODUCTS AFFECTED

G500H TXi systems installed using G500H TXi Part 27 AML STC SR02622SE are affected.

WARRANTY INFORMATION

This modification is warranty reimbursable with a deadline of February 29, 2024.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

DOCUMENTATION CONSIDERATIONS

There are no recommended RFMS or Pilot’s Guide changes applicable to this bulletin. Applicable RFMS and ICA documents listed in Table 1, are required to be issued to the aircraft owner/operator before the aircraft is returned to service, if not already provided.

Table 1

Document Title	Part Number	Revision
G500H TXi Part 27 AML STC Maintenance Manual	190-02401-01	3
RFMS G500H TXi P27 AML STC	190-02401-02	5

At time of publication the current G500(H)/G600/G700 TXi Pilot’s Guide (P/N 190-01717-10) is Rev. N.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin’s authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.