



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G500H TXi Owner and Operators
DATE: January 4, 2024
SUBJECT: Approval of GDU™ 700 Display and GDU 1060 -X2 Part Numbers and G500H TXi Main Software Version 3.53
CERTIFICATION AUTHORIZATION: STC SR02622SE MDL Rev 12

COMPLIANCE

Optional: STC Service Bulletin 24004 may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

This STC Service Bulletin provides notification of an update to STC SR02622SE, G500H TXi Part 27 STC MDL Revision 12.

Major details of the update are:

- Approved -X2 GDU 700 and GDU 1060 Part Numbers



NOTE

Minimum GDU Main Software Version 3.53 and Boot Version 2.10 are both required for these part numbers. -X2 units are shipped from the factory with these software versions.

- Updated G500/G600 TXi main software to Software Version 3.53, which fixes an issue where the traffic page On Scene annunciation was not legible

PRODUCTS AFFECTED

G500H TXi systems installed using G500H TXi Part 27 AML STC SR02622SE are affected.

WARRANTY INFORMATION

This modification is not warranty reimbursable.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

DOCUMENTATION CONSIDERATIONS

There are no recommended RFMS or Pilot's Guide changes applicable to this bulletin. Applicable RFMS and ICA documents listed in Table 1, are required to be issued to the aircraft owner/operator before the aircraft is returned to service, if not already provided.

Table 1

Document Title	Part Number	Revision
G500H TXi Part 27 AML STC Maintenance Manual	190-02401-01	3
RFMS G500H TXi P27 AML STC	190-02401-02	5

At time of publication the current G500(H)/G600/G700 TXi Pilot's Guide (P/N 190-01717-10) is Rev. N.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.