



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GI 275 Owners and Operators
DATE: August 1, 2024
SUBJECT: GI 275 Multi-function Instrument System Software Version 3.20
CERTIFICATION AUTHORIZATION: TSO Authorization

TSO authorization does not provide installation airworthiness approval. Separate installation airworthiness approval is required for type certified aircraft. Notification of revision to any Garmin STC(s) will be provided under a separate service bulletin.

COMPLIANCE

Garmin TSO Service Bulletin 24030 is optional and may be incorporated at the owner's discretion.

PURPOSE



CAUTION

GI 275 Software Version 3.20 prevents the display of VOR deviations from a composite NAV source. GI 275 Composite NAV pins are J2751 Pin 5 and Pin 44.

GI 275 Multi-function Instrument System Software Version 3.20 provides the following updates:

- Added interface support for the GTR™ 205 COM Transceiver and GNC® 215 Radio
- Added configurable inverted Airspeed tape
- Added ARINC 429 sourced TAT
- Added support for 7-cylinder engines
- Updated Mag Cal procedure to 30 degree increments
- Added customizable ADAHRS Sensor Names
- Added a secondary field overlay on the altitude tape to show current altitude in the alternate units (meters/feet)
- Various Database related improvements

PRODUCTS AFFECTED

GI 275 Multi-function Instruments with System Software Version 3.10 or earlier are affected.

© 2024 Garmin Ltd. or its subsidiaries.

This work is licensed under a

[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

WARRANTY INFORMATION

This modification is not warranty reimbursable.

DOCUMENTATION CONSIDERATIONS

GI 275 Pilot's Guide (190-02246-01) Rev Q has been updated to reflect GI 275 Multi-function Instrument System Software Version 3.20.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.