



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: GTR™ 205 COM Transceiver/GNC® 215 VHF NAV/COM Radio
Owners and Operators

DATE: January 27, 2025

SUBJECT: GTR™ 205 COM Transceiver/GNC® 215 VHF NAV/COM Radio Main Software
Version 2.22

**CERTIFICATION
AUTHORIZATION:** TSO Authorization

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

GTR 205/GNC 215 Main Software Version 2.22 adds the following:

- 2-place intercom system (GTR and GNC)
- 3D audio (GTR 205 only)
- Bluetooth media and calling (GTR 205 only)
- Improved interface to G3X Touch for radio and audio controls (GTR 205 only)
- Auxiliary audio inputs for other radios, alerts, music, etc (GTR 205 only)
- Allow frequency information to come from an external LRU instead of a database in the GTR/GNC

PRODUCTS AFFECTED

GTR 205 and GNC 215 products listed below are affected.

Table 1. Product Affected

Model	Appliance P/N
GTR 205	011-05287-00
GNC 215	011-05289-00

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

WARRANTY INFORMATION

This modification is not warranty reimbursable.

DOCUMENTATION CONSIDERATIONS

The GTR 205/GNC 215 Pilot's Guide (Garmin P/N 190-02766-02) Rev B has been released to reflect changes in Software Version 2.22 and is to be provided to the owner/operator.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.