



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 25013 Rev A

TO: SL 30/40 Owners and Operators
DATE: March 31, 2025
SUBJECT: SL 30/40 End of Repair Service Life

PRODUCTS AFFECTED

SL 30/40 units are affected.

ISSUE

Based on the availability of parts, repair services will be discontinued for the products listed above at the end of 2025.

We sincerely regret discontinuing service or support for any Garmin product. However, a number of components required for the manufacture and/or repair of essential subassemblies within the affected products are no longer available.

Please visit www.Garmin.com/aviation for your product replacement needs.

© 2025 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 4.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/4.0/)..