

# SERVICE ADVISORY

NO.: 0617

**TO:** All Garmin Aviation Service Centers

**DATE:** 9 August 2006

**SUBJECT:** Temporary Flight Restriction (TFR)

# **PURPOSE**

Garmin would like to remind pilot's flying with GDL 69/69A equipped aircraft that TFR's are advisory in nature only and are not a replacement for a thorough preflight briefing on TFR times and locations.

# **DISPOSITION**

Always confirm TFR data through official sources and contact your local Flight Service Station for interpretation of TFR data.

## **APPROVAL**

Information contained in the advisory does not affect the airworthiness of the GDL 69/69A.

#### AFMS AND PILOT'S GUIDE CONSIDERATIONS

N/A

# **PRODUCT AFFECTED**

All GDL 69/69A equipped aircraft.