



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GTN 650/750 Owner/Operators
DATE: March 8, 2012

SUBJECT: This communication is intended to inform Garmin aviation customers of forthcoming service document Service Bulletin 1203: GTN 650 and GTN 750 Notification of Mod Level 1.

COMPLIANCE

Mandatory

PURPOSE

Some GTN 650 and GTN 750 Navigation Systems require either upgrading to Mod Level 1 to improve the reliability of the VHF navigation receiver, or marking of Mod Level 1 on the serial tag to indicate the previously upgraded, but unmarked Mod Level status.

PRODUCTS AFFECTED

All GTN 650/750 Units that have not been verified as having been upgraded to Mod 1.

DESCRIPTION

Service Bulletin 1203 provides instructions to inspect the serial number of the GTN 650/750 to determine its disposition as related to the Mod Level 1 requirement.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.