



## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered Garmin Owners/Operators

**DATE:** 4 January 2013

**SUBJECT:** GMA 350/350H Software Version 3.05

### **COMPLIANCE**

Recommended

### **PURPOSE**

Software Version 3.05 for GMA 350/350H contains the following changes:

- Improved compatibility with KFC/KAP autopilot systems (resolves the issue described in Garmin Installation Bulletin 1213)
- Adjusted relative volume during 3D Audio mode

### **PRODUCT AFFECTED**

This bulletin is applicable to all GMA 350/350H units with Software Version 2.11 or previous software versions that are not installed as part of a Garmin Integrated Flight Deck System.

The unit's current software version is viewed using the GMA 350/350H Configuration Tool. Contact your local Garmin dealer for details.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.