

## AVIATION SERVICE DOCUMENT NOTIFICATION

**TO:** Registered Garmin GTN 6XX/7XX Owner/Operators

**DATE:** April 29, 2014

SUBJECT: COM version 2.13 update for GTN Part 23 AML STC SA02019SE-D

**CERTIFICATION** 

**APPROVAL:** STC (see Approval section of STC SB 1418 for details)

COMPLIANCE Recommended.

## **PURPOSE**

This service document provides notification of amendment of STC SA02019SE-D. This STC amendment approves GTN COM board software version 2.13.

## **PRODUCTS AFFECTED**

GTN 635/650/750 units installed under the GTN Part 23 AML STC SA02019SE-D are eligible for this software update.

## **DESCRIPTION**

The GTN COM board software version 2.13 incorporates the following changes:

- Reduced noise burst (open squelch) that can occur after transmitting, flip-flopping frequencies, or exiting monitor mode when the receiver is set for high sensitivity.
- Corrected issue in limited circumstances where a monitored COM frequency may prevent the pilot from receiving communication on the active COM frequency (Service Advisory 1370)

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.