



AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Registered Garmin GDL 84/88 Owner and Operators
DATE: October 4, 2016
SUBJECT: GDL 84/88 software version 3.34 update for Part 23 AML STC SA02119SE
CERTIFICATION
APPROVAL: STC SA02119SE MDL Revision 11

COMPLIANCE

Optional

PURPOSE

STC SA02119SE MDL Revision 11 includes GDL 84/88 software version 3.34.

Software version 3.34 contains the following changes from version 3.33:

- METARs with missing cloud data will show on the interfaced display as grey flags instead of cyan to properly identify the missing information
- Improved Air/Ground determination for all aircraft with a G500/G600 system, GTN 6XX/7XX, or GNS 4XXW/5XXW

PRODUCTS AFFECTED

GDL 84/88 units installed under the GDL 84/88 Part 23 AML STC SA02119SE are affected.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.