

## AVIATION SERVICE DOCUMENT NOTIFICATION

TO:Owners of Record of GTX 3X5(R) Series ProductsDATE:February 24, 2017

SUBJECT:GTX 3X5(R) Series Main Software Version 2.10 and ADS-B Software Version 2.10CERTIFICATIONTSO

## **COMPLIANCE**

Optional

## PURPOSE

GTX 3X5(R) Series main software version 2.10 includes the following changes:

- Added Enhanced Surveillance capability for European customers
- Fixed Altitude Source Selection configuration for GTN and G9XX/G1XXX retrofit installations
- Added support for MAPX GPS Output
- Added three Transponder Control formats

GTX 3X5(R) Series ADS-B software version 2.10 filters out TAS/TCAS targets determined to be on the ground. This reduces nuisance alerts around airports.

## PRODUCTS AFFECTED

All GTX 3X5(R) series products listed below (with main software version 2.09 or earlier and/or ADS-B software version 2.05 or earlier) that are interfaced to a TAS/TCAS are affected.

Model	Appliance P/N
GTX 335	011-03300-0()
GTX 335 NV	011-03300-2()
GTX 335 GPS	011-03300-4()
GTX 335R	011-03301-0()
GTX 335R GPS	011-03301-4()
GTX 345	011-03302-0()
GTX 345 GPS	011-03302-4()
GTX 345R	011-03303-0()
GTX 345R GPS	011-03303-4()

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.