



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin G1000® equipped Textron Aviation 172R/S, (T)182T, (T)206H, G36 and G58 owner/operators

DATE: July 25, 2022

SUBJECT: G1000 NXi Hardware and Software update for G1000-equipped Textron Aviation 172R/S, (T)182T, (T)206H, G36 and G58 airplanes

CERTIFICATION AUTHORIZATION: STC SA01830WI

COMPLIANCE

Optional: This Service Bulletin may be incorporated at the owner's discretion and is not warranty reimbursable.

PURPOSE

New Hardware:

- NXi display hardware:
 - GDU™ 1050 for 172R/S aircraft without autopilot
 - GDU 1054B for 172R/S (with autopilot), (T)182T, and (T)206H aircraft
 - GDU 1050 and 1055 for G36 and G58 aircraft
- Flight Stream 510 for data streaming and database updates
- GTX™ 345R (Optional)



NOTE

For installations with a GTX 33 non-ES, a GTX 3X5(R) or GTX 33 ES is required.

G1000 NXi System Software Versions 2501.02, 2780.03, and 2788.04 provide the following new features:

- NEXRAD Animation
- Visual Approach support
- Flight Plan auto-nomination
- Transition to Approach
- SurfaceWatch™
- Vertical Situation Display
- HSI map
- Visual Reporting Points
- IFR/VFR maps
- Dual charts to allow pilot selection of FliteCharts® or ChartView™ for display

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.

PRODUCTS AFFECTED

The following systems are affected:

- G1000 WAAS systems with System Software Versions 0563.03 through 0563.36 installed in Textron Aviation 172R/S, (T)182T, and (T)206H aircraft
- G1000 WAAS systems with System Software Versions 0857.05 through 0857.10 installed in Textron Aviation G58 aircraft
- G1000 WAAS systems with System Software Versions 0858.05 through 0858.10 installed in Textron Aviation G36 aircraft

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.