



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 22003 Rev B

TO: GTN™ Xi Owners and Operators
DATE: January 27, 2023
SUBJECT: Graphical Flight Plan Editing
REVISION B: Added Resolution

PRODUCTS AFFECTED

All GTN Xi navigators are affected.

ISSUE

The flight plan will not change when airborne and using the graphical flight plan editing feature on the active leg of a flight plan that contains an altitude constraint.

ACTION

When airborne, do not graphically edit the active leg of a flight plan if it contains an altitude constraint.

RESOLUTION

This issue has been fixed in GTN Xi Main Software Version 20.30. Refer to Garmin TSO Service Bulletin 22108.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/)..