

## AVIATION SERVICE DOCUMENT NOTIFICATION

TO:	G500/G600 TXi Owner and Operators
DATE:	June 30, 2022
SUBJECT:	G500/G600 TXi Approval of Garmin GPT Pressure Sensors
CERTIFICATION AUTHORIZATION:	STC SA02571SE

## **COMPLIANCE**

Optional: STC Service Bulletin 22062 may be incorporated at the owner's discretion.

## PURPOSE

This STC Service Bulletin provides notification of an update to the AML STC SA02571SE Master Drawing List (MDL) Revision 22. This change includes installation of the Garmin GPT Pressure Sensors for piston engine Fuel, Oil, and Manifold Pressure Gauges. This MDL revision also provides updated RPM Gauge Markings for the Piper PA-46-500TP.

## PRODUCTS AFFECTED

G500/G600 TXi PFD/MFD/EIS display systems installed using Approved Model List (AML) Supplemental Type Certificate (STC) SA02571SE are affected.

Please contact your local Garmin Avionics Dealer (http://www.garmin.com/dealers/) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.