



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

SERVICE ADVISORY

NO.: 23001 Rev A

TO: Garmin GTN™ 6XX/7XX, GPS 175, GNC® 355, GNX™ 375,
G500(H)/G600/G700 TXi, and GI 275 Owners and Operators

DATE: January 27, 2023

SUBJECT: Database Sync

PRODUCTS AFFECTED

Garmin GTN 6XX/7XX (Software Versions 6.72 or earlier) or GPS 175/GNC 355/GNX 375 (Software Versions 3.20 or earlier) interfaced to G500(H)/G600/G700 TXi (Software Versions 3.50 or later) or GI 275 (Software Versions 2.60 or later) are affected.



NOTE

GTN Xi units are not affected.

ISSUE

Database syncing from the GTN 6XX/7XX and GPS 175/GNC355/GNX 375 to the G500(H)/G600/G700 TXi and GI 275 is not supported.

ACTION

Do one of the following:

- Load databases in the G500(H)/G600/G700 TXi to sync them to the GTN 6XX/7XX and GPS 175/GNC355/GNX 375
- Load databases in the GI 275 to sync them to the GPS 175/GNC355/GNX 375
- Load databases in each LRU individually.

RESOLUTION

This will be fixed in future GTN 6XX/7XX and GPS 175/GNC 355/GNX 375 software versions.

© 2023 Garmin Ltd. or its subsidiaries.

This work is licensed under a
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/).