



1200 E. 151<sup>st</sup> Street  
Olathe, KS 66062  
913-397-8200

## SERVICE ADVISORY

NO.: 23052 Rev B

**TO:** G3000® and G5000® Owners and Operators  
**DATE:** December 3, 2024 (Originally Issued May 10, 2023)  
**SUBJECT:** Weather Radar Display Range  
**REVISION B:** Updated Resolution

---

### **PRODUCTS AFFECTED**

G3000 and G5000 airframes with GDU™ Software Version 30.99 and earlier with GWX Auto Mode enabled are affected.



### **NOTE**

GDU Software Version 21.15 is not affected by this issue.

### **ISSUE**

Changing the weather radar display range on one display can change the weather radar display range on other displays.

### **PILOT ACTION**

Enable the HSI Map on the PFD.

### **RESOLUTION**

This has been fixed in GDU Software Version 31.00. Contact the TC/STC holder for applicability.

© 2024 Garmin Ltd. or its subsidiaries.

This work is licensed under a  
[Creative Commons Attribution-NonCommercial-NoDerivs 3.0 Unported License](https://creativecommons.org/licenses/by-nc-nd/3.0/)..