



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GDL® 84H/88H Owner and Operators
DATE: June 28, 2023
SUBJECT: Approval of GDL® 84H/88H Main Software Version 3.43
**CERTIFICATION
AUTHORIZATION:** STC SR02123SE MDL Revision 2

COMPLIANCE

Recommended: Garmin recommends the incorporation of STC Service Bulletin 23064 at the next scheduled service interval.

PURPOSE

This STC Service Bulletin provides notification of an update to STC SR02123SE MDL Revision 2 that includes main software version 3.43.

GDL 84H/88H main software version 3.43 corrects an issue where some 1090ES ADS-B and ADS-R surface targets may erroneously appear as directional.

PRODUCTS AFFECTED

GDL® 84H/88H installed under Part 27 AML STC SR02123SE are affected.

WARRANTY INFORMATION

This modification is warranty reimbursable with a deadline of December 31, 2023.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.